

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: North Platte I-24 Pad

Loc ID: 429060

Inspection: 713900195



Exhibit A



Exhibit B



Exhibit C



Exhibit D

CA: This location does not comply with Rule 1002.f. Sediment traps around the perimeter of the well location are overgrown with tumbleweeds and unconsolidated with straw wattles being degraded and rendered ineffective. The operator shall repair installed BMP's per Rule 1002.f.

CA Resolution: Operator has addressed weeds and tumbleweeds and repaired identified sediment traps to comply with Rule 1002.f.