

Inspection Photos
Location Name: Vera McCannon 1
Location ID: 317643




Photo 1 riser at valve house on treater not ID or tagged




Photo 2 riser at treater not ID or tagged

Inspection Photos
Location Name: Vera McCannon 1
Location ID: 317643



Photo 3 generator and bitcoin collector



Photo 4 gas measurement for generator

Inspection Photos
Location Name: Vera McCannon 1
Location ID: 317643



Photo 5 riser in tank berm not ID or tagged



Photo 6 tank signage faded / peeling

Inspection Photos
Location Name: Vera McCannon 1
Location ID: 317643



Photo 7 manway cover NE oil tank



Photo 8 manway cover NW oil tank

Inspection Photos
Location Name: Vera McCannon 1
Location ID: 317643



Photo 9 water tank valve need plug



Photo 10 leak on water tank drain valve

Inspection Photos
Location Name: Vera McCannon 1
Location ID: 317643



Photo 11 plug valve on SE oil tank