

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/26/2024

Submitted Date:

01/30/2024

Document Number:

707602314**FIELD INSPECTION FORM**

Loc ID 309693	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: _____ 9 Number of Comments _____ 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>100322</u> Name of Operator: <u>NOBLE ENERGY INC</u> Address: <u>2001 16TH STREET SUITE 900</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290808	WELL	TA	10/01/2019	OW	123-25247	MENONI B 30-17	TA

General Comment: This is a WELL inspection. Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down. Centralized Battery serves 2 Location IDs (336566, 309693). (Well(s): 3: Temporarily Abandoned TA ;1: Plugged & Abandoned PA). Centralized Battery Formerly served 1 Location ID (323726). (Well(s): 1: Plugged & Abandoned PA). Centralized Battery serves 1 Tank Battery Facility ID (Pending). Reference (Associated Well(s), Battery Inspections): A.) Field Inspection Report doc. #707602312 and/or Location ID #336566 for TA Well(s) info. B.) Field Inspection Report doc. #707602314 and/or Location ID #309693 for TA Well(s) info. C.) Field Inspection Report doc. #707602316 and/or Location ID #336566 for PA Well(s) info. D.) Field Inspection Report doc. #707602318 and/or Location ID #323726 for PA Well(s) info. E.) Field Inspection Report doc. #707602320 and/or Location ID #336566 for Battery / Facility, Equipment info.

Location**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Iron panel. Concrete barriers.		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead: w/ Master & casing valves.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.372180,-104.584070
Comment:	Centralized Battery serves 2 Location IDs (336566, 309693). (Well(s): 3: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected FacilitiesFacility ID: 290808 Type: WELL API Number: 123-25247 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.
Locked-Out, Tagged-Out | LOTO.
OOSLAT applied at flowline valve.
Blue TA, Black NEWS tag(s) posted.
CECMC records last production: 03/2019.

Form 4 on file. TA date: 04/07/2019. Approved.
DH-CIBP set.
Form 21 MIT on file. MIT date: 09/10/2019. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 03/07/2019. Approved.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 09/01/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input type="text"/>						Date: <input type="text"/>
Corrective Action: <input type="text"/>						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On FRI 01/26/2024 at approximately 16:43 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: MENONI B-65N64W/30SWNE Location ID: 309693 Well Name(s): Menoni B 30-17. API: 123-25247. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Routine inspection.</p>	evinsb	01/30/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602315	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6412626