

Inspection Photos
Location Name: Energy Minerals Unit A1
Location ID: 311333



Photo 1 Location



Photo 2 Wellsite Tall dead vegetation around the ROW.

Inspection Photos
Location Name: Energy Minerals Unit A1
Location ID: 311333



Photo 3 WH.



Photo 4 WH sign.

Inspection Photos
Location Name: Energy Minerals Unit A1
Location ID: 311333



Photo 5 Tall dead vegetation around the ancillary equip.



Photo 6 Tall dead vegetation around the ancillary equip.