

Final Reclamation Inspection

January 26, 2024

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 321522

Inspection Document #: 697505081

Broomfield County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: GREEN MA-61S68W 17NWNE

Location ID: 321522



Photo 1. Photo taken from the well location, facing Northwest. Photo illustrates a land use change to housing development.



Inspection Photos
 Location Name: GREEN MA-61S68W 17NWNE
 Location ID: 321522



CIV - 321522- GREEN MA
Map Extent - Overview

Imagery: RS Orthomosaic & DSM
 Imagery Date: 13 Sep 2022
 Map Date: 08 Nov 2022
 Datum: NAD_1983_UTM_Zone_13N
 POC: Soil Sage

Legend

- ◆ Wells
- Disturbance Extent
- Road
- Flowline

0 0.01 0.01 0.02 Miles

Overall Disturbance:
 0.91 Acres
 Scale: 1:600

Pad Location:
 39.969970
 -105.022280



Photo 2. Photo illustrates Operator supplied drone imagery illustrating the location disturbance extent as it relates to the housing development.

