

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SOLVAY-67S96W/2NWSW

Location ID: 334726

Date: 1/29/2024



Location Entrance – Photo #08892



Wellheads – Photo #08897



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SOLVAY-67S96W/2NWSW

Location ID: 334726

Date: 1/29/2024



Wellhead – Photo #08893



Separators – Photo #08894



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SOLVAY-67S96W/2NWSW

Location ID: 334726

Date: 1/29/2024



**Tank Battery – Photo #08895**



**Lack of Stabilization/Insufficient Vehicle Tracking BMPs at  
Location Entrance/Exit – Photo #08898**