

Inspection Photos

API: 043-06194

Operator: **INCREMENTAL OIL & GAS (FLORENCE) LLC**

Inspection Date: 1/18/2024

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest toward the wellsite location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:417859 | Date: 1/18/2024

Inspection Photos



Photo 2. Facing southeast toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:417859 | Date: 1/18/2024

Inspection Photos



Photo 3. Facing back northwest. There is an offsite tank battery shown at red arrow.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:417859 | Date: 1/18/2024

Inspection Photos



Photo 4. Standing at the tank battery facing south. The well is shown at red arrow. The flowline does not appear to be registered.



Inspection Photos



Photo 5. Facing southwest toward the offsite tank battery which has 6 tanks. There is not a proper sign posted at the tank battery.

