

Interim and Stormwater Inspection

January 10, 2024

Operator: Kerr McGee Oil & Gas- #47120

Location ID: 317773

Inspection Document #: 7094007136

Weld County, CO

SWSW Section 14 T1N R67W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Francis D. Clark B-1 & tank
Battery
Location ID: 317773



Photo 1. Photo taken of location sign at wellhead, facing north.



Photo 2. Photo taken of tank battery on pad. Photo taken facing west.



Inspection Photos

Location Name: Francis D. Clark B-1 & tank
Battery
Location ID: 317773




Photo 3. Photo taken of wellhead. Photo taken facing southwest..



Photo 4. Photo taken of stormwater erosion on access road to site. Photo taken facing southeast.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400736

Inspection Photos

Location Name: Francis D. Clark B-1 & tank
Battery
Location ID: 317773



Photo 5. Photo taken of equipment and mowed vegetation on site. Photo taken facing northeast.



Photo 6. Photo of mowed vegetation on site, and vegetation on adjacent land. Photo taken facing east.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400736