

Interim and Stormwater Inspection

January 23, 2024

Operator:Extraction Oil & Gas- #10459

Location ID: 319761

Inspection Document #: 709400738

Adams County, CO

NENE Section 31 T1S R65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Box Elder 1 H & tank Battery
Location ID: 319761




Photo 1. Photo taken of location sign, facing north.



Photo 2. Photo taken of tank battery on pad. Photo taken facing west.



Inspection Photos
Location Name: Box Eder 1 H & tank Battery
Location ID: 319761



Photo 3. Photo taken of wellhead. Photo taken facing southwest..



Photo 4. Photo taken of weeds (russian thistle) along access road into pad. Photo taken facing southeast.

Inspection Photos
Location Name: Box Eder 1 H & tank Battery
Location ID: 319761



Photo 5. Photo taken of weeds (russian thistle & Kochia) and vegetation on site. Photo taken facing southwest.



Photo 6. Photo of weeds (russian thistle & Kochia). Photo taken facing south.