

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type: UNUSED EQUIPMENT

Comment: unused/disconnected gas meter on previous tank battery location. See attached photos.

Corrective Action: **Comply with Rule 606.**

Date: 02/07/2024

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Gas Meter Run

1

corrective date

Comment:

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary WEATHER CONDITIONS: sunny, dry ground. On Wednesday, January 31, 2024 at approximately 10:40, I, Inspector Brittani Santistevan, conducted an on-site inspection at EASTON 2, G12-19 (Noble Energy, Inc.), at location ID: 322600 in WELD COUNTY, Colorado. While there, I observed a plugged and abandoned location. During this inspection the following possible compliance issues were observed: 1. It appears the wellheads associated with this equipment has been plugged and abandoned, unused/disconnected gas meter remains on tank battery location. Remove to comply with Rule 606. (Corrective Action Date: February 7, 2024) See attached photo #3.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	01/31/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714200628	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6413843