

**Operator: Crestone Peak Resources**

**Location Name: McPeck SESW Multi Well Pad 0-6-10**

**Loc ID: 422467**

**Inspection: 702402754**



Exhibit A



**Exhibit B**



**Exhibit C**

**CA:** Sign not posted or information inaccurate at well(s). Install sign to comply with Rule 605.a.

**CA Resolution:** Sign has been installed to comply with Rule 605.a.

**CA:** Stained soils on the west side of the condensate tanks load line. Properly dispose of oily waste in accordance with Rule 905.e.

**CA Resolution:** Oily waste has been disposed of to comply with Rule 905.e.

**CA:** North Tank is rusted, pitted, or show evidence of inadequate repair. Stained soil under pitted hole in tank. Inspect, maintain, and repair tanks to comply with rule 609.b.

**CA Resolution:** Tanks has been repaired to comply with Rule 609.b.