

Inspection Photos
Location Name: Sam Funakoshi A1
Location ID: 318417



Photo 1 Location.



Photo 2 WH.

Inspection Photos
Location Name: Sam Funakoshi A1
Location ID: 318417



Photo 3 WH sign.

Photo 4 Ancillary equip.

Inspection Photos
Location Name: Sam Funakoshi A1
Location ID: 318417



Photo 5 Flow line manifold.



Photo 6 Horizontal Heated Separator.

Inspection Photos
Location Name: Sam Funakoshi A1
Location ID: 318417



Photo 7 Gas Meter Run, card indicates calibration is not current.

Photo 8 TB sign.

Inspection Photos
Location Name: Sam Funakoshi A1
Location ID: 318417



Photo 7 Gas Meter Run, card indicates calibration is not current.