

**Inspection Photos**  
**Location Name: Wells Ranch USX AE 31-99HZ Tank Battery**  
**Location ID: 431553**



**Photo 1 – Separators and ECDs**



**Photo 2 – Fence in disrepair**





**Inspection Photos**  
**Location Name: Wells Ranch USX AE 31-99HZ Tank Battery**  
**Location ID: 431553**



**Photo 3 – Separators and Gas Meter House**



**Photo 4 – Fence in disrepair and Tumbleweeds**



## Inspection Photos

Location Name: Wells Ranch USX AE 31-99HZ Tank Battery

Location ID: 431553



**Photo 5 – Back Side of Tank Battery**



**Photo 6 – Tank Battery – Tumbleweeds**



Inspection Photos  
Location Name: Wells Ranch USX AE 31-99HZ Tank Battery  
Location ID: 431553



Photo 7 – Capacity Sign missing



Photo 8 – Tank Battery Sign



Inspection Photos  
Location Name: Wells Ranch USX AE 31-99HZ Tank Battery  
Location ID: 431553



Photo 9 – Tank Battery Sign



Photo 10 – Tank Battery Sign

**Inspection Photos**  
**Location Name: Wells Ranch USX AE 31-99HZ Tank Battery**  
**Location ID: 431553**



**Photo 11 – Tank Battery**