

Final Reclamation and Stormwater Inspection

Date: 1/30/24

Operator: PDC Energy Inc. - 69175

Location ID: 330117

Inspection Document #: 713900330

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Swafford 11-11
Location ID: 330117



Photo 1. The photo was taken from the entrance to the well location facing Southeast. The photo illustrates the area has been mowed and a gate remains at the entrance.



Photo 2. The photo was taken from the access road to the well location facing Southeast. The photo illustrates an overview of the tank battery and well location.

Inspection Photos

Location Name: Swafford 11-11

Location ID: 330117



Photo 3. The photo was taken from the well location facing North. The photo illustrates the well location has been mowed and has some evidence of seeding rows.

Photo 4. The photo was taken from the well location facing East. Refer to the comment from photo 3.

Inspection Photos
Location Name: Swafford 11-11
Location ID: 330117



Photo 5. The photo was taken from the well location facing South. Refer to the comment from photo 3.

Photo 6. The photo was taken from the well location facing West. Refer to the comment from photo 3.

Inspection Photos
Location Name: Swafford 11-11
Location ID: 330117



Photo 7. The photo was taken from the well location facing South. Refer to the comment from photo 3.



Photo 8. The reference photo was taken from near the well location facing North. The photo illustrates rabbitbrush, yucca, sand dropseed, etc.