

Inspection Photos
Firecracker Consolidation
Spill ID 481413



Photo 1 – Open excavation/weeds/fencing



Photo 2 - Open excavation/weeds

Inspection Photos
Firecracker Consolidation
Spill ID 481413



Photo 3 – Open excavation/weeds



Photo 4 - Open excavation/weeds

**Inspection Photos
Firecracker Consolidation
Spill ID 481413**



Photo 5 – Open excavation/weeds



Photo 6 - Soil stockpile/weeds

**Inspection Photos
Firecracker Consolidation
Spill ID 481413**



Photo 7 – Soil stockpile/weeds



Photo 8 - Soil stockpile/weeds

Inspection Photos
Firecracker Consolidation
Spill ID 481413



Photo 9 – Trash in field



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources