

Inspection Photos

Location Name: CONAGRA B-65N64W/30NWSE

Location ID: 302259



Photo #1

Conagra B 30-22 (123-28032) Wellsite

Plugged & Abandoned | PA

Cut / Capped

Abandoned flowline valve remains on site



Photo #2

Conagra B 30-21, 30-18, 30-24 Battery site

Inactive | Shut-down

Formerly served:

Conagra B 30-22, Menoni B30-7, B30-10 ;

Plugged & Abandoned | PA

Equipment Documented; Loc ID: 302258



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources