

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/26/2024

Submitted Date:

01/31/2024

Document Number:

707602324**FIELD INSPECTION FORM**Loc ID 302257 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297668	WELL	TA	11/14/2019	OW	123-28030	CONAGRA B 30-24	TA

General Comment:

This is a WELL inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 3 Location IDs

(302258, 302257, 336617).

(Well(s): 3: Temporarily Abandoned | TA ;1: Plugged & Abandoned | PA).

Centralized Battery Formerly served 2 Location IDs

(302259, 323732).

(Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID

(Pending).

Reference (Associated Well(s), Battery Inspections):

A.) Field Inspection Report doc. #707602322 and/or Location ID #302258
for TA Well(s) info.B.) Field Inspection Report doc. #707602324 and/or Location ID #302257
for TA Well(s) info.C.) Field Inspection Report doc. #707602326 and/or Location ID #336617
for TA Well(s) info.D.) Field Inspection Report doc. #707602328 and/or Location ID #302259
for PA Well(s) info.E.) Field Inspection Report doc. #707602330 and/or Location ID #336617
for PA Well(s) info.F.) Field Inspection Report doc. #707602332 and/or Location ID #302258
for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Wellhead: w/ Master & casing valves.		
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	Temporarily Abandoned TA. Equipment removed.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.369793,-104.589691

Comment:		Centralized Battery serves 3 Location IDs (302258, 302257, 336617). (Well(s): 3: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).			
Corrective Action:					Date:
<u>Paint</u>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
<u>Venting:</u>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 297668

Type: WELL

API Number: 123-28030

Status: TA

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.
Locked-Out, Tagged-Out | LOTO.
OOSLAT applied at flowline valve.
Blue TA tag posted.
CECMC records last production: 08/2017.

Form 4 on file. TA date: 04/17/2019. Approved.
DH-CIBP set.
Form 21 MIT on file. MIT date: 07/23/2019. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 07/31/2019. Approved.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/27/2023

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 6

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On FRI 01/26/2024 at approximately 16:09 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: CONAGRA B-65N64W/30NWSE Location ID: 302257 Well Name(s): Conagra B 30-24. API: 123-28030. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Routine inspection.</p>	evinsb	01/31/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602325	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6414480