

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/26/2024

Submitted Date:

01/31/2024

Document Number:

707602326**FIELD INSPECTION FORM**

Loc ID 336617	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
------------------	--------------------------------	---------------------------------------------	-------------------

**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**

☐ THIS IS A FOLLOW UP INSPECTION

☐ FOLLOW UP INSPECTION REQUIRED

☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

15 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296715	WELL	TA	10/01/2019	OW	123-26874	CONAGRA B 30-18	TA

**General Comment:**

This is a WELL inspection.  
Well(s): 1: Temporarily Abandoned | TA.  
Battery: Inactive | Shut-down.

Centralized Battery serves 3 Location IDs  
(302258, 302257, 336617).  
(Well(s): 3: Temporarily Abandoned | TA ;1: Plugged & Abandoned | PA).

Centralized Battery Formerly served 2 Location IDs  
(302259, 323732).  
(Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID  
(Pending).

Reference (Associated Well(s), Battery Inspections):  
A.) Field Inspection Report doc. #707602322 and/or Location ID #302258 for TA Well(s) info.  
B.) Field Inspection Report doc. #707602324 and/or Location ID #302257 for TA Well(s) info.  
C.) Field Inspection Report doc. #707602326 and/or Location ID #336617 for TA Well(s) info.  
D.) Field Inspection Report doc. #707602328 and/or Location ID #302259 for PA Well(s) info.  
E.) Field Inspection Report doc. #707602330 and/or Location ID #336617 for PA Well(s) info.  
F.) Field Inspection Report doc. #707602332 and/or Location ID #302258 for Battery / Facility, Equipment info.

## Location

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 0		
Comment:	Equipment Assigned to Loc ID #302258.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:	Equipment Assigned to Loc ID #302258.		
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	Temporarily Abandoned   TA. Equipment removed.		
Corrective Action:		Date:	
Type: Emission Control Device	# 0		
Comment:	Equipment Assigned to Loc ID #302258.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	

Type: Other	# 1	
Comment:	Wellhead: w/ Master & casing valves.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.369793,-104.589691
Comment:	Centralized Battery serves 3 Location IDs (302258, 302257, 336617). (Well(s): 3: Temporarily Abandoned   TA).  Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:	Equipment Assigned to Loc ID #302258.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment:	Equipment Assigned to Loc ID #302258.				
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**Facility ID: 296715 Type: WELL API Number: 123-26874 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.  
Disconnected from flowline.  
Locked-Out, Tagged-Out | LOTO.  
OOSLAT applied at flowline valve.  
Blue TA tag posted.  
CECMC records last production: 08/2017.

Form 4 on file. TA date: 04/11/2019. Approved.  
DH-CIBP set.  
Form 21 MIT on file. MIT date: 07/23/2019. Approved.  
Form 6A on file. Out-of-Svc Designation.  
Date: 08/16/2017. Approved.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 08/27/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On FRI 01/26/2024 at approximately 15:55 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: MENONI-65N64W/30SWNE Location ID: 336617 Well Name(s): Conagra B 30-18. API: 123-26874. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned   TA. Battery: Inactive   Shut-down.</p> <p>Routine inspection.</p>	evinsb	01/31/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602327	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6414481">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6414481</a>