

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/26/2024

Submitted Date:

01/31/2024

Document Number:

707602328

FIELD INSPECTION FORM

Loc ID 302259 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297670	WELL	TA	08/01/2019	OW	123-28032	CONAGRA B 30-22	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Battery: Inactive | Shut-down.

Centralized Battery serves 3 Location IDs (302258, 302257, 336617).
(Well(s): 3: Temporarily Abandoned | TA ;1: Plugged & Abandoned | PA).

Centralized Battery Formerly served 2 Location IDs (302259, 323732).
(Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):
A.) Field Inspection Report doc. #707602322 and/or Location ID #302258 for TA Well(s) info.
B.) Field Inspection Report doc. #707602324 and/or Location ID #302257 for TA Well(s) info.
C.) Field Inspection Report doc. #707602326 and/or Location ID #336617 for TA Well(s) info.
D.) Field Inspection Report doc. #707602328 and/or Location ID #302259 for PA Well(s) info.
E.) Field Inspection Report doc. #707602330 and/or Location ID #336617 for PA Well(s) info.
F.) Field Inspection Report doc. #707602332 and/or Location ID #302258 for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

Equipment:				corrective date
Type: Plunger Lift	# 0			
Comment:	Plugged & Abandoned PA. Equipment removed.			
Corrective Action:				Date:
Type: Flow Line	# 1			
Comment:	Flowline valve present at wellsite.			
Corrective Action:				Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 297670 Type: WELL API Number: 123-28032 Status: TA Insp. Status: PA

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On FRI 01/26/2024 at approximately 15:38 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: CONAGRA B-65N64W/30NWSE Location ID: 302259 Well Name(s): Conagra B 30-22. API: 123-28032. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Inactive Shut-down.</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6-SRA Pending. Plugging, cut/cap date: 01/22/2024. Form 27-I on file. 06/16/2023. Approved. Form 6-NIA on file. 05/08/2023. Approved. Form 42 Notice PA on file. 11/01/2023. Approved. Form 17 Brhd test on file. 11/01/2023. Approved. Surface plug date: 11/01/2023. Cut / capped: 01/22/2024. Plugged & Abandoned PA well GPS coordinates: 40.369975 / -104.587964</p> <p>Routine inspection.</p>	evinsb	01/31/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602329	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6414482