

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/26/2024

Submitted Date:

01/31/2024

Document Number:

707602330**FIELD INSPECTION FORM**Loc ID 336617 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Binschus, Chris		chris.binschus@state.co.us	
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245627	WELL	PA	06/24/2019	OW	123-13422	MENONI B30-7	RI

General Comment:

This is a **PLUGGED & ABANDONED WELL / RECLAMATION** inspection.
 This is a Final Reclamation Inspection for PA Well API# 123-13422, on an active location.
 Well(s) were plugged and abandoned | PA on 06/24/2019.
 Well(s): 1: Plugged & Abandoned | PA.
 Battery: Inactive | Shut-down.

Centralized Battery serves 3 Location IDs
 (302258, 302257, 336617).
 (Well(s): 3: Temporarily Abandoned | TA ;1: Plugged & Abandoned | PA).

Centralized Battery Formerly served 2 Location IDs
 (302259, 323732).
 (Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID
 (Pending).

Reference (Associated Well(s), Battery Inspections):
 A.) Field Inspection Report doc. #707602322 and/or Location ID #302258
 for TA Well(s) info.
 B.) Field Inspection Report doc. #707602324 and/or Location ID #302257
 for TA Well(s) info.
 C.) Field Inspection Report doc. #707602326 and/or Location ID #336617
 for TA Well(s) info.
 D.) Field Inspection Report doc. #707602328 and/or Location ID #302259
 for PA Well(s) info.
 E.) Field Inspection Report doc. #707602330 and/or Location ID #336617
 for PA Well(s) info.
 F.) Field Inspection Report doc. #707602332 and/or Location ID #302258
 for Battery / Facility, Equipment info.

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No
Comment:

☐ Multiple Spills and Releases?

Equipment:

Type: Plunger Lift	# 0		corrective date
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:			Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	245627	Type:	WELL	API Number:	123-13422	Status:	PA	Insp. Status:	RI

--

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: **Operator has PLUGGED & ABANDONED | PA the above well(s) on an active location; therefore, this is a well release on an active location. This inspection confirms that one (1) well(s) remain at the location. Refer to the attached inspection photo(s).**

Corrective Action: _____ Date _____

Inspector Name: Evins, Bret

Overall Final Reclamation	Pass	Well Release on Active Location <input checked="" type="checkbox"/>	Multi-Well Location <input checked="" type="checkbox"/>
---------------------------	------	---	---

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On FRI 01/26/2024 at approximately 15:50 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: MENONI-65N64W/30SWNE Location ID: 336617 Well Name(s): Menoni B30-7. API: 123-13422. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Inactive Shut-down.</p> <p>WELL STATUS COMMENT: Menoni B30-7 (123-13422) Plugged & Abandoned PA. Form 6S on file. Plugging, cut/cap date: 06/24/2019. Approved. Plugged & Abandoned PA well GPS coordinates: 40.371750 / -104.590310</p> <p>Routine inspection.</p>	evinsb	01/31/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602331	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6414483