











WGS84 40 10772 -104.98226 ft 4975 NW314  
±16ft ±11ft ±13

**KPK**  
K.P. KAUFFMAN COMPANY, INC.  
Pace Connelly 3  
NE SE Sec. 27, T2N, R68W  
Weld County, Colorado  
I-25 (West Frontage Road) & Highway 52  
In case of emergency call 303-825-4822



© 26 Jan 24 10:30:59 AM  
ECMC Environmental Inspection Pace Connelly 3









WGS84  
±16ft

40.10772, -104.98226

ft  
±11ft

4976

°T  
±13

N4



Stained Soil  
© 26-Jan-24 10:31:05 AM  
ECMC Environmental Inspection Pace Connelly 3





WGS84  
±16ft

40.10772, -104.98226

Alt  
4979

4979

NE33

NE33



© 26-Jan-24 10:31:09 AM  
ECMC Environmental Inspection Pace Connelly 3





















Inadequate fencing  
© 26-Jan-24 10:31:50 AM  
ECMC Environmental Inspection Pace Connelly 3





Inadequate fencing  
Ⓢ 26-Jan-24 10:31:56 AM  
ECMC Environmental Inspection Pace Connelly 3





Inadequate fencing  
© 26-Jan-24 10:32:00 AM  
ECMC Environmental Inspection Pace Connelly.3



















WGS84 40.10771, -104.98573  $\pm 16\text{ft}$  4991  $\pm 11\text{ft}$  NE43  $\pm 13$



© 26-Jan-24 10:38:58 AM  
ECMC Environmental Inspection Pace Connelly 8





Leaking equipment  
© 26-Jan-24 10:39:09 AM  
ECMC Environmental Inspection Pace Connelly 8





© 26-Jan-24 10:39:34 AM  
ECMC Environmental Inspection Pace Connolly 8






























Leaky equipment  
© 26-Jan-24 10:42:00 AM  
Pace Connelly 8 ECMC Environmental Inspection













WGS84 40.10766, -104.98482  $\Delta$  <sup>ft</sup> 4985  $\Delta$  <sup>°T</sup> N2  
±15ft ±12ft ±28



© 26-Jan-24 11:15:36 AM  
ECMC Environmental Inspection Pace Connelly 8



WGS84  $\pm 15\text{ft}$  40.10766, -104.98482  $\wedge^{\text{ft}}_{\pm 12\text{ft}}$  4987  $\triangle^{\circ, \text{T}}_{\pm 28}$  N348



© 26-Jan-24 11:15:41 AM  
ECMC Environmental Inspection Pace Connelly 8