

**KT Resources LLC
Ant Hill Unit 18-42
Loc ID: 316308**



As signs are replaced additional information will be required




As signs are replaced additional information will be required



KT Resources LLC
Ant Hill Unit 18-42
Loc ID: 316308



Debris from 5/10/23 inspection



Gas meter calibration out of compliance

**KT Resources LLC
Ant Hill Unit 18-42
Loc ID: 316308**



Location from Northeast corner



Location from Northwest corner

**KT Resources LLC
Ant Hill Unit 18-42
Loc ID: 316308**



Location from Southwest corner



Location from Southeast corner