


KT Resources LLC
Ant Hill Unit 24-14
Loc ID: 316313



As signs are replaced additional information will be required



Gas meter calibration out of compliance

**KT Resources LLC
Ant Hill Unit 24-14
Loc ID: 316313**



Debris



As signs are replaced additional information will be required

KT Resources LLC
Ant Hill Unit 24-14
Loc ID: 316313



Oily waste on the ground out from wellhead



Oily waste on the ground out from wellhead

**KT Resources LLC
Ant Hill Unit 24-14
Loc ID: 316313**



Oily waste on tank and on the ground



Oily waste on tank and on the ground

**KT Resources LLC
Ant Hill Unit 24-14
Loc ID: 316313**



Location from Southwest corner



Location from Southeast corner

**KT Resources LLC
Ant Hill Unit 24-14
Loc ID: 316313**



Location from Northeast corner



Location from Northwest corner