

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N PARACHUTE/WF08D-26H26A596

Location ID: 335642

Date: 1/30/2024



**Location Entrance – Photo #08901**



**Wellheads/Sediment Encroachment – Photo #08903**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N PARACHUTE/WF08D-26H26A596

Location ID: 335642

Date: 1/30/2024



Separator/Unused Equipment – Photo #08902



Tank Battery – Photo #08905

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N PARACHUTE/WF08D-26H26A596

Location ID: 335642

Date: 1/30/2024



Tank Overrun by Sediment – Photo #08906



Tank Overrun by Sediment – Photo #08908

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N PARACHUTE/WF08D-26H26A596

Location ID: 335642

Date: 1/30/2024



Tank Overrun by Sediment – Photo #08907



Tank Overrun by Sediment – Photo #08910

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N PARACHUTE/WF08D-26H26A596

Location ID: 335642

Date: 1/30/2024



**Secondary Containment/Production Equipment Overrun by Sediment – Photo #08909**