

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 1-W-20 Pad

Location ID: 335242



Photo # 4358 From entrance to location



Photo # 4359 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 1-W-20 Pad

Location ID: 335242



Photo # 4360 Location



Photo # 4361 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 1-W-20 Pad

Location ID: 335242



Jan 29, 2024 at 10:15:14 AM
CO



Jan 29, 2024 at 10:16:36 AM
CO

Photo # 4362 Location

Photo # 4363 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 1-W-20 Pad

Location ID: 335242



Photo # 4364 Location



Photo # 4365 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 1-W-20 Pad

Location ID: 335242



Photo # 4366 Location



Photo # 4367 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 1-W-20 Pad

Location ID: 335242



Photo # 4368 Location



Photo # 4369 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 1-W-20 Pad

Location ID: 335242



Photo # 4370 Unused equipment/ECD disconnected



Photo # 4371 Unused equipment/ECD disconnected

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 1-W-20 Pad

Location ID: 335242



Photo # 4372 Knock out drum for ECD disconnected from tanks



Photo # 4373 Unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 1-W-20 Pad

Location ID: 335242



Photo # 4374 Unused equipment



Photo # 4375 Production tank lacks required labeling

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 1-W-20 Pad

Location ID: 335242



Photo # 4376 Production tank lacks required labeling




Photo # 4377 Production tank lacks required labeling