

Inspection Photos

Location Name: Wells Ranch USX AE 31-01P Tank Battery

Location ID: 431556



Photo 1 – ECDs



Photo 2 – Separators – Tumbleweeds

Inspection Photos

Location Name: Wells Ranch USX AE 31-01P Tank Battery

Location ID: 431556



Photo 3 – Fence in disrepair



Photo 4 – Tank Battery

Inspection Photos
Location Name: Wells Ranch USX AE 31-01P Tank Battery
Location ID: 431556



Energy and Carbon Management Commission
40.4468, -104.36047, 4674.1ft
01/30/2024 13:26:17



Energy and Carbon Management Commission
40.44681, -104.36057, 4682.1ft
01/30/2024 13:26:49

Photo 5 – Tank Battery Sign

Photo 6 – Tank Battery Sign