

Inspection Photos

Loc: 379317

Operator: MURFIN DRILLING COMPANY INC

Inspection Date: 1/30/2024

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south toward the reclaimed location.



Inspection Photos



Photo 2. Facing north at the location. Perennial vegetation has established throughout the location.



Inspection Photos



Photo 3. Facing east at the location. Perennial vegetation has established throughout the location.



Inspection Photos



Photo 4. Facing north at the location. Perennial vegetation has established throughout the location. The pipe previously observed in this area has been removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:379317 | Date: 1/30/2024