

Interim and Stormwater Inspection

January 10, 2024

Operator: KP Kauffman Company- #46290

Location ID: 317645

Inspection Document #: 709400742

Weld County, CO

SWNE Section 3 T1N R67W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Jack Berger #1
Facility ID: 317645



Photo 1. Photo taken of location sign, facing north.



Photo 2. Photo taken of pump jack. Photo taken facing northwest.



Inspection Photos
Location Name: Jack Berger #1
Facility ID: 317645



Photo 3. Photo taken of mowed/harvested crop the well is located in and unmanaged weeds (kopchia & russian thistle) on pad site. Photo taken facing southeast.



Photo 4. Photo taken of unmanaged weeds (kopchia & russian thistle) along access road and around electrical boxes. Photo taken facing north.



Inspection Photos
Location Name: Jack Berger #1
Facility ID: 317645




Photo 5. Photo taken of wellhead, no staining observed. Photo taken facing southeast.



Photo 6. Photo taken of access road stormwater erosion. . Photo taken facing northwest.