

Caerus  
P26NWB  
Location ID: 335365



Separators



Separators

Caerus  
P26NWB  
Location ID: 335365



ECD



Well heads and Location shows lack of stabilization

Caerus  
P26NWB  
Location ID: 335365



Location entrance shows lack of stabilization



Location shows lack of stabilization

Caerus  
P26NWB  
Location ID: 335365



Location shows lack of stabilization



Well heads with some gravel

Caerus  
P26NWB  
Location ID: 335365



Location shows lack of stabilization



Location shows lack of stabilization

Caerus  
P26NWB  
Location ID: 335365



Entrance to access road to locations

Caerus  
P26NWB  
Location ID: 335365



Tracking BMP needs maintained