

Caerus  
P26NW  
Location ID: 335249



Separators



Well heads



Caerus  
P26NW  
Location ID: 335249




Tank battery



Debris and fencing



Caerus  
P26NW  
Location ID: 335249



Debris and fencing



Debris



Caerus  
P26NW  
Location ID: 335249



Location shows lack of stabilization



Location entrance shows lack of stabilization and tracking



Caerus  
P26NW  
Location ID: 335249



Access road entrance



Access road entrance tacking BMP's need maintained