

Final Reclamation Inspection

January 26, 2024

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 320336

Inspection Document #: 697505092

Adams County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: NORTH HURON-61S68W 22NWNW

Location ID: 320336



Photo 1. Photo taken from the well location, facing South. Well location meets Rule 1004 standards.



Photo 2. Photo taken from the tank battery location, facing West. Photo illustrates a land use change and a recent disturbance, likely for the land use change and sidewalk construction.

Inspection Photos

Location Name: NORTH HURON-61S68W 22NWNW

Location ID: 320336



Photo 3. Photo taken from the tank battery location, facing North. See comments under Photo 2.



Photo 4. Photo taken from the tank battery location, facing Northwest. See comments under Photo 2.

Inspection Photos
Location Name: NORTH HURON-61S68W 22NWNW
Location ID: 320336



Photo 5. Photo taken from the tank battery location, facing North. See comments under Photo 2.