

**Operator: HIGHPOINT OPERATING CORPORATION**

**Location Name: Pappenheim SW 6-62-23**

**Loc ID: 432385**

**Inspection: 696305501**



Exhibit A



**Exhibit B**

**CA:** All 4 Tanks missing Labels - Content, Capacity and NFPA. Install sign to comply with Rule 605.h.

**CA Resolution:** Operator has installed appropriate signage on the identified tanks to comply with Rule 605.h.





Exhibit A





Exhibit B



Exhibit C





**Exhibit D**

**CA:** Unmarked OOSLAT Risers at Tanks, Separator, ECD and Wellhead. See photos. Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.

**CA Resolution:** Operator has added tags to all identified Risers to comply with Rule 1105.