

# Inspection Photos

Loc: 309301

Operator: OGRIS OPERATING LLC

Inspection Date: 1/31/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northwest along the maintained road.



## Inspection Photos



**Photo 2.** Facing northwest toward the location.



Inspection Photos



**Photo 3.** Facing northwest toward interim reclamation which has established vegetation.



## Inspection Photos



**Photo 4.** Facing toward the well and pit. Lined pit is adequately fenced..

