

Inspection Photos

Loc: 309119

Operator: OGRIS OPERATING LLC

Inspection Date: 1/31/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest toward the access road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309119 | Date: 1/31/2024

Inspection Photos



Photo 2. Facing southwest toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309119 | Date: 1/31/2024

Inspection Photos



Photo 3. Facing southwest toward the fill slope which has established vegetation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309119 | Date: 1/31/2024