

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/31/2024

Submitted Date:

02/02/2024

Document Number:

701008094

FIELD INSPECTION FORMLoc ID 310972 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10274

Name of Operator: PLATINUM GAS PROPERTIES LLC

Address: 6946 COUNTY RD T

City: KIRK State: CO Zip: 80824

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|--------------|------------------|---------|
| Brenner, Roger | 970-362-4204 | argwmd@yahoo.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 297308 | WELL | PR | 12/18/2008 | GW | 125-11365 | SIMMONS 34-11 | PR |

General Comment:

Routine Inspection

Location**Lease Road:**

| | | | |
|-------------------|-----------------------------|-------|--|
| Type | Access | | |
| comment: | Gravel road through pasture | | |
| Corrective Action | L | Date: | |

Overall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|---|-------|------------|
| Type | WELLHEAD | | |
| Comment: | Lease sign by wellhead | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Metal sign by water tank with no labeling | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 02/29/2024 |

Emergency Contact Number:

| | | | |
|--------------------|--|--|-------------|
| Comment: | | | |
| Corrective Action: | | | Date: _____ |

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|---|-------|--|
| Type | WELLHEAD | | |
| Comment: | Metal panels around wellhead and metal shed | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------------|--------------------------------------|-------|-----------------|
| | | | corrective date |
| Type: Vertical Separator | # 1 | | |
| Comment: | Vertical gas separator in metal shed | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|--------------------|--|----------|----------------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | OTHER | PBV FIBERGLASS | | 39.891230,-102.160520 |
| Comment: | Fiberglass water tank 50% buried 650' SW of wellhead next to CR 22 | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | | | | |
|------------------|----------|--|--|--|--|
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | 120bbbls | | | | |

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Other (Type) | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Venting: | | | | | |
| Yes/No | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|--|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 297308 | Type: | WELL | API Number: | 125-11365 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Casing production. Central meter run for (Simmons 34-11, 43-11, 44-11, Peters 44-10) 2500' W @ Peters 44-10 (39.89297/-102.16793) | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other | Pass | Compaction | Pass | | | |

Comment: Location is grassed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| | | |
|--------------|----------------|---|
| Document Num | Description | URL |
| 701008095 | location photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6417242 |