

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad

Location ID: 334081



Jan 30, 2024 at 10:25:22 AM
CO

Photo # 4696 From entrance to location



Jan 30, 2024 at 10:30:54 AM
CO

Photo # 4697 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081



Photo # 4698 Location



Photo # 4699 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad

Location ID: 334081



Photo # 4700 Location



Photo # 4701 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad

Location ID: 334081




Photo # 4702 Location



Photo # 4703 Tank battery lacks required signage

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081



Photo # 4704 Tank battery lacks required signage



Photo # 4705 Tank battery lacks required signage

Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081



Photo # 4706 Tank labels have inaccurate information/lack required information




Photo # 4707 Tank labels have inaccurate information/lack required information

Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad

Location ID: 334081



Photo # 4708 Open ended load line



Photo # 4709 Open ended load line



Inspection Photos
Location Name: CAERUS PICEANCE LLC FEDERAL 8C Pad
Location ID: 334081



Photo # 4710 Unused equipment



Photo # 4711 Unused equipment