

Inspection Photos

Location Name: Wells Ranch USX AE 31-09P Tank Battery

Location ID: 431555



Photo 1 – ECDs and Separators



Photo 2 – Gas Meters


Inspection Photos
Location Name: Wells Ranch USX AE 31-09P Tank Battery
Location ID: 431555



Photo 3 – Tank Battery

Photo 4 – Tank Battery Sign

Inspection Photos
Location Name: Wells Ranch USX AE 31-09P Tank Battery
Location ID: 431555



Energy and Carbon Management Commission
40.43968, -104.36074, 4645.4ft
01/30/2024 14:04:49




Energy and Carbon Management Commission
40.43968, -104.36067, 4639.5ft
01/30/2024 14:04:56

Photo 5 – Tank Battery Sign

Photo 6 – Tank Battery

Inspection Photos
Location Name: Wells Ranch USX AE 31-09P Tank Battery
Location ID: 431555



Energy and Carbon Management Commission
40.43967, -104.36064, 4645.5ft
01/30/2024 14:05:06



Energy and Carbon Management Commission
40.43968, -104.3606, 4647.5ft
01/30/2024 14:05:09

Photo 7 – Tank Battery Sign

Photo 8 – Tank Battery