

Inspection Photos

Location Name: MENONI-65N64W/30SWSE

Location #: 332724



Photo #1

Menoni B30-15 (123-13424) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 10 yds.



Photo #2

Conagra B 30-23XD, Menoni B30-15 Battery site

Abandoned: ALL Equipment Removed



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources