

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/26/2024

Submitted Date:

02/02/2024

Document Number:

707602346

FIELD INSPECTION FORM

Loc ID 332724 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections
Binschus, Chris		chris.binschus@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245629	WELL	PA	06/19/2019	GW	123-13424	MENONI B30-15	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / RECLAMATION** inspection.
This is a Final Reclamation Inspection for PA Well API#123-13424, on an active location.
Well(s) were plugged and abandoned | PA on 06/19/2019.
Well(s): 1: Plugged & Abandoned | PA.
Battery: Abandoned. ALL equipment has been removed.
Abandoned Battery SE corner GPS coordinates: 40.364280 / -104.590031

Abandoned Centralized Battery formerly served 1 Location ID (332724).
(Well(s): 2: Plugged & Abandoned | PA).

Inspected Facilities

Facility ID: 245629 Type: WELL API Number: 123-13424 Status: PA Insp. Status: PA

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: Operator has PLUGGED & ABANDONED | PA the above well(s) on an active location; therefore, this is a well release on an active location. This inspection confirms that zero (0) well(s) remain at the location. Refer to the attached inspection photo(s).

Corrective Action: _____

Date _____

Overall Final Reclamation Pass Well Release on Active Location Multi-Well Location **COGCC Comments**

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On FRI 01/26/2024 at approximately 15:18 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: MENONI-65N64W/30SWSE Location ID: 332724 Well Name(s): Menoni B30-15. API: 123-13424. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.364280 / -104.590031</p> <p>WELL STATUS COMMENT: Menoni B30-15 (123-13424) Plugged & Abandoned PA. Form 6-SRA on file. Plugging, cut/cap date: 06/19/2019. Approved. Plugged & Abandoned PA well GPS coordinates: 40.364600 / -104.590290</p> <p>Routine inspection.</p>	evinsb	02/02/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602347	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6417664