

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S96W/22SENE

Location ID: 335786

Date: 1/30/2024



Location Entrance – Photo #08929



Wellheads – Photo #08936

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S96W/22SENE

Location ID: 335786

Date: 1/30/2024



Gas Meters – Photo #08930



Separator/Meter/Gas Lift – Photo #08932

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S96W/22SENE

Location ID: 335786

Date: 1/30/2024



Unsecured Meter Housing – Photo #08934