

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N PARACHUTE/WF02D-26 B26596

Location ID: 335600

Date: 1/30/2024



Location Entrance – Photo #09000



Wellheads – Photo #09001

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N PARACHUTE/WF02D-26 B26596

Location ID: 335600

Date: 1/30/2024



Separators – Photo #09005



Gas Lift – Photo #09002

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N PARACHUTE/WF02D-26 B26596

Location ID: 335600

Date: 1/30/2024



Tank Battery – Photo #09004