

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. Parachute/WF H26 596

Location ID: 415372

Date: 1/30/2024



Location Entrance – Photo #09007



Wellheads – Photo #09011

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. Parachute/WF H26 596

Location ID: 415372

Date: 1/30/2024



Gas Meters – Photo #09012



Gas Lift – Photo #09008



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. Parachute/WF H26 596

Location ID: 415372

Date: 1/30/2024



Gas Lift – Photo #09009



Pig Station – Photo #09013