

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2024

Submitted Date:

02/02/2024

Document Number:

708301624

FIELD INSPECTION FORM

Loc ID 415372	Inspector Name: Morris, Matthew	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 9 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																																																																																							
Operator Information: OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202																																																																																																																											
Contact Information: <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>, CAERUS</td> <td></td> <td>COGCC.inspections@caerus oilandgas.com</td> <td></td> </tr> </table>				Contact Name	Phone	Email	Comment	, CAERUS		COGCC.inspections@caerus oilandgas.com		ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE																																																																																																															
Contact Name	Phone	Email	Comment																																																																																																																								
, CAERUS		COGCC.inspections@caerus oilandgas.com																																																																																																																									
Inspected Facilities: <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>415326</td><td>WELL</td><td>PR</td><td>01/05/2012</td><td>GW</td><td>045-19024</td><td>N. PARACHUTE WF06A-26H26596</td><td>PR</td></tr> <tr><td>415331</td><td>WELL</td><td>PR</td><td>02/22/2012</td><td>GW</td><td>045-19027</td><td>N. PARACHUTE WF14B-26H26596</td><td>PR</td></tr> <tr><td>415333</td><td>WELL</td><td>PR</td><td>01/05/2012</td><td>GW</td><td>045-19028</td><td>N. PARACHUTE WF04A-35H26596</td><td>PR</td></tr> <tr><td>415339</td><td>WELL</td><td>PR</td><td>11/25/2011</td><td>GW</td><td>045-19031</td><td>N. PARACHUTE WF03A-25H26596</td><td>PR</td></tr> <tr><td>415340</td><td>WELL</td><td>PR</td><td>01/08/2012</td><td>GW</td><td>045-19032</td><td>N. Parachute WF11C-26 H26 59</td><td>PR</td></tr> <tr><td>415345</td><td>WELL</td><td>PR</td><td>01/05/2012</td><td>GW</td><td>045-19035</td><td>N. Parachute WF13C-24 H26 59</td><td>PR</td></tr> <tr><td>415350</td><td>WELL</td><td>PR</td><td>02/22/2012</td><td>GW</td><td>045-19036</td><td>N. Parachute WF05C-26 H26 59</td><td>PR</td></tr> <tr><td>415356</td><td>WELL</td><td>PR</td><td>01/02/2012</td><td>GW</td><td>045-19039</td><td>N. Parachute WF05B-26 H26 59</td><td>PR</td></tr> <tr><td>415357</td><td>WELL</td><td>PR</td><td>02/07/2012</td><td>GW</td><td>045-19040</td><td>N. Parachute WF04B-25 H26 59</td><td>PR</td></tr> <tr><td>415362</td><td>WELL</td><td>PR</td><td>01/05/2012</td><td>GW</td><td>045-19042</td><td>N. PARACHUTE WF03B-35H26596</td><td>PR</td></tr> <tr><td>415363</td><td>WELL</td><td>PR</td><td>02/22/2012</td><td>GW</td><td>045-19043</td><td>N. Parachute WF06D-26 H26 59</td><td>PR</td></tr> <tr><td>415373</td><td>WELL</td><td>PR</td><td>12/05/2011</td><td>GW</td><td>045-19045</td><td>N. PARACHUTE WF14B-24H26596</td><td>PR</td></tr> <tr><td>415378</td><td>WELL</td><td>PR</td><td>02/07/2012</td><td>GW</td><td>045-19047</td><td>N. PARACHUTE WF04C-25H26596</td><td>PR</td></tr> <tr><td>415379</td><td>WELL</td><td>PR</td><td>03/09/2012</td><td>GW</td><td>045-19048</td><td>N. PARACHUTE WF12B-26H26596</td><td>PR</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	415326	WELL	PR	01/05/2012	GW	045-19024	N. PARACHUTE WF06A-26H26596	PR	415331	WELL	PR	02/22/2012	GW	045-19027	N. PARACHUTE WF14B-26H26596	PR	415333	WELL	PR	01/05/2012	GW	045-19028	N. PARACHUTE WF04A-35H26596	PR	415339	WELL	PR	11/25/2011	GW	045-19031	N. PARACHUTE WF03A-25H26596	PR	415340	WELL	PR	01/08/2012	GW	045-19032	N. Parachute WF11C-26 H26 59	PR	415345	WELL	PR	01/05/2012	GW	045-19035	N. Parachute WF13C-24 H26 59	PR	415350	WELL	PR	02/22/2012	GW	045-19036	N. Parachute WF05C-26 H26 59	PR	415356	WELL	PR	01/02/2012	GW	045-19039	N. Parachute WF05B-26 H26 59	PR	415357	WELL	PR	02/07/2012	GW	045-19040	N. Parachute WF04B-25 H26 59	PR	415362	WELL	PR	01/05/2012	GW	045-19042	N. PARACHUTE WF03B-35H26596	PR	415363	WELL	PR	02/22/2012	GW	045-19043	N. Parachute WF06D-26 H26 59	PR	415373	WELL	PR	12/05/2011	GW	045-19045	N. PARACHUTE WF14B-24H26596	PR	415378	WELL	PR	02/07/2012	GW	045-19047	N. PARACHUTE WF04C-25H26596	PR	415379	WELL	PR	03/09/2012	GW	045-19048	N. PARACHUTE WF12B-26H26596	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																				
415326	WELL	PR	01/05/2012	GW	045-19024	N. PARACHUTE WF06A-26H26596	PR																																																																																																																				
415331	WELL	PR	02/22/2012	GW	045-19027	N. PARACHUTE WF14B-26H26596	PR																																																																																																																				
415333	WELL	PR	01/05/2012	GW	045-19028	N. PARACHUTE WF04A-35H26596	PR																																																																																																																				
415339	WELL	PR	11/25/2011	GW	045-19031	N. PARACHUTE WF03A-25H26596	PR																																																																																																																				
415340	WELL	PR	01/08/2012	GW	045-19032	N. Parachute WF11C-26 H26 59	PR																																																																																																																				
415345	WELL	PR	01/05/2012	GW	045-19035	N. Parachute WF13C-24 H26 59	PR																																																																																																																				
415350	WELL	PR	02/22/2012	GW	045-19036	N. Parachute WF05C-26 H26 59	PR																																																																																																																				
415356	WELL	PR	01/02/2012	GW	045-19039	N. Parachute WF05B-26 H26 59	PR																																																																																																																				
415357	WELL	PR	02/07/2012	GW	045-19040	N. Parachute WF04B-25 H26 59	PR																																																																																																																				
415362	WELL	PR	01/05/2012	GW	045-19042	N. PARACHUTE WF03B-35H26596	PR																																																																																																																				
415363	WELL	PR	02/22/2012	GW	045-19043	N. Parachute WF06D-26 H26 59	PR																																																																																																																				
415373	WELL	PR	12/05/2011	GW	045-19045	N. PARACHUTE WF14B-24H26596	PR																																																																																																																				
415378	WELL	PR	02/07/2012	GW	045-19047	N. PARACHUTE WF04C-25H26596	PR																																																																																																																				
415379	WELL	PR	03/09/2012	GW	045-19048	N. PARACHUTE WF12B-26H26596	PR																																																																																																																				

415382	WELL	PR	03/09/2012	GW	045-19049	N. Parachute WF12A-26 H26 59	PR
415387	WELL	PR	01/08/2012	GW	045-19050	N. PARACHUTE WF12C- 26H26596	PR

General Comment:

COGCC Inspection Report Summary

On 1/30/2024 at approximately 13:35, Compliance Inspector Matthew Morris conducted an on-site inspection at CAERUS PICEANCE LLC, N. Parachute/WF H26 596 at Location ID #415372 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

1) No wellhead signs posted

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	No wellhead signs posted.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	03/03/2024

Emergency Contact Number:

Comment:	911/(970) 285-2615		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas meters/lift protected by concrete barriers.		
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 3		corrective date
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 16		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 16		

Inspected Facilities									
Facility ID:	415326	Type:	WELL	API Number:	045-19024	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	415331	Type:	WELL	API Number:	045-19027	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	415333	Type:	WELL	API Number:	045-19028	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	415339	Type:	WELL	API Number:	045-19031	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	415340	Type:	WELL	API Number:	045-19032	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	415345	Type:	WELL	API Number:	045-19035	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	415350	Type:	WELL	API Number:	045-19036	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	415356	Type:	WELL	API Number:	045-19039	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			

Facility ID:	415357	Type:	WELL	API Number:	045-19040	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:									
Corrective Action:						Date:			
Facility ID:	415362	Type:	WELL	API Number:	045-19042	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:									
Corrective Action:						Date:			
Facility ID:	415363	Type:	WELL	API Number:	045-19043	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:									
Corrective Action:						Date:			
Facility ID:	415373	Type:	WELL	API Number:	045-19045	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:									
Corrective Action:						Date:			
Facility ID:	415378	Type:	WELL	API Number:	045-19047	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:									
Corrective Action:						Date:			
Facility ID:	415379	Type:	WELL	API Number:	045-19048	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:									
Corrective Action:						Date:			
Facility ID:	415382	Type:	WELL	API Number:	045-19049	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:									
Corrective Action:						Date:			
Facility ID:	415387	Type:	WELL	API Number:	045-19050	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:									
Corrective Action:						Date:			

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Compaction						
		Culverts				
		Check Dams				
		Rip Rap				
		Berms				
Ditches						
		Gravel				
		Ditches				
		Sediment Traps				
				Material Handling And Spill Prevention		Chemical tanks in secondary containment

Comment: Location surface is frozen. Unable to inspect all Stormwater BMPs due to snow cover.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708301625	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6417742