

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 27-44 (27P) Pad

Location ID: 334317



Photo # 5303 From entrance to location




Photo # 5304 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 27-44 (27P) Pad

Location ID: 334317



Photo # 5305 Location




Photo # 5306 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 27-44 (27P) Pad

Location ID: 334317

Feb 1, 2024 at 2:20:07 PM



Photo # 5307 Location

Feb 1, 2024 at 2:16:50 PM



Photo # 5308 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 27-44 (27P) Pad

Location ID: 334317



**Photo # 3550 From inspection 708902863 conducted on 01/23/2024 Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife**

**Photo # 5309 Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife**