

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Location Overview: Location is within High Priority/Black Bear/NSO Habitat areas. Location is approximately 86 yards from Pete & Bill creek.

Section/Township/Range: 8 8S95W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Photo # 4664 Lack of stabilization/compaction



Photo # 4665 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Photo # 4666 Lack of stabilization/compaction



Photo # 4667 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Photo # 4668 Lack of stabilization/compaction



Photo # 4669 Lack of stabilization/compaction



Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Jan 30, 2024 at 10:11:20 AM
CO

Photo # 4670 Lack of stabilization/compaction



Jan 30, 2024 at 10:17:38 AM
CO

Photo # 4671 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Photo # 4672 Lack of stabilization/compaction



Photo # 4673 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Photo # 4674 Lack of stabilization/compaction



Photo # 4675 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Photo # 4676 Lack of stabilization/compaction