

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34F-795 Pad

Location ID: 334384



Photo # 5334 From entrance to location



Photo # 5335 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34F-795 Pad

Location ID: 334384



Photo # 5336 Location



Photo # 5337 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34F-795 Pad

Location ID: 334384




Photo # 5338 Location



Photo # 5339 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34F-795 Pad

Location ID: 334384



Photo # 8923 From inspection 708902473 conducted on 12/07/2023 Wellhead lacks required signage




Photo # 5340 Wellhead lacks required signage

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34F-795 Pad

Location ID: 334384



Photo # 8924 From inspection 708902473 conducted on 12/07/2023 Wellhead lacks required signage



Photo # 5341 Wellhead lacks required signage



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 34F-795 Pad

Location ID: 334384




Photo # 5342 Wellhead lacks required signage




Photo # 5343 Wellhead lacks required signage