

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403676151

Date Received:
02/04/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 17210
Name of Operator: CINNAMON CREEK OIL & GAS INC
Address: P O BOX 544
City: WALSH State: CO Zip: 81090

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Mills, Rick	719-324-5630/719-353-2523	rickmills000@gmail.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 695109060
Inspection Date: 01/24/2024 FIR Submit Date: 01/24/2024 FIR Status:

Inspected Operator Information:

Company Name: CINNAMON CREEK OIL & GAS INC Company Number: 17210
Address: P O BOX 544
City: WALSH State: CO Zip: 81090

LOCATION - Location ID: 322267

Location Name: HASSLER-DOC DAVIS-620S69W Number: 21SWSE County: FREMONT
Qtrqr: SWSE Sec: 21 Twp: 20S Range: 69W Meridian: 6
Latitude: 38.286890 Longitude: -105.110420

FACILITY - API Number: 05-043-00 Facility ID: 210090

Facility Name: HASSLER-DOC DAVIS Number: 1
Qtrqr: SWSE Sec: 21 Twp: 20S Range: 69W Meridian: 6
Latitude: 38.286890 Longitude: -105.110420

CORRECTIVE ACTIONS:

1 CA# 191340

Corrective Action: Tanks will function as sealed and ventless with gas released only through a vapor control system or properly sized pressure relief valve. per Rule 608.a.(9). 24 HOURS TO INSTALL PRESSURE RELEIF VALVE.

Date: 01/25/2024

Response: CA COMPLETED Date of Completion: 01/30/2024

Operator Comment: Operator installed proper PRV on top of tank. See "Attachment" tab for image of PRV installation.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Operator is responding to FIR Doc #695109060, Inspector noted that "RISER ON TANK IS OPEN TO ATMOSPHERE." Operator immediately dispatched a crew to install proper "PRV" on top of tank. This FIRR further responds to Inspector's comment regarding bradenhead test, and advises that Operator is seeking a variance to bradenhead testing on the Hassler Doc Davis 1 well, a turn of the century completion (1910), with wellbore construction consisting of casing strings clamped or welded on without bradenhead access. Operator is concerned about hot-tapping an access into the casing and potentially damaging the casing which would in turn compromise the well integrity. At this time, there is no measurable pressure or observation of fugitive gas from the well, indicating the casing is securely isolating hydrocarbon migration.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Rick Mills

Signed: _____

Title: Owner

Date: 2/4/2024 6:39:50 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403676160	Image of PRV installation on top of tank
403676162	Wellbore diagram

Total Attach: 2 Files