

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 1 – Spill area 1/25/2024 AM

Photo 2 - Spill area 1/25/2024 AM

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 3 – Spill area 1/25/2024 AM

Photo 4 - Spill area 1/25/2024 AM

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 5 – Spill area 1/25/2024 AM



Photo 6 - Spill area 1/25/2024 AM

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 7 – Spill area 1/25/2024 AM



Photo 8 - Spill area 1/25/2024 AM

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 9 – Spill area 1/25/2024 AM



Photo 10 - Spill area 1/25/2024 AM

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 11 – Soil stockpile 1/25/2024 AM



Photo 12 - Soil stockpile 1/25/2024 AM

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 13 – Spill area 1/25/2024 PM



Photo 14 - Spill area 1/25/2024 PM



Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 15 – Spill area 1/25/2024 PM



Photo 16 - Spill area 1/25/2024 PM

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 17 – Open excavation 1/25/2024 PM



Photo 18 - Open excavation 1/25/2024 PM

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939




Photo 19 – Spill area 1/26/2024

Photo 20 - Spill area 1/26/2024

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 21 – Soil stockpile 1/26/2024



Photo 22 - Soil stockpile 1/26/2024

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 23 – Spill area 1/29/2024



Photo 24 - Spill area 1/29/2024

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 25 – Spill area 1/29/2024



Photo 26 - Spill area 1/29/2024

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 27 - Open excavation 1/29/2024



Photo 28 - Open excavation 1/29/2024

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 29 - Open excavation 1/29/2024



Photo 30 - Open excavation 1/29/2024

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 31 – Soil stockpile 1/29/2024



Photo 32 - Spill area 1/30/2024

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 33 – Spill area 1/30/2024



Photo 34 - Spill area 1/30/2024

**Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939**



Photo 35 – Open excavation 1/30/2024



Photo 36 - Open excavation 1/30/2024



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 37 – Open excavation 1/30/2024



Photo 38 - Open excavation 1/30/2024

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 39 – Open excavation 1/30/2024



Photo 40 - Open excavation 1/30/2024

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 41 – Open excavation 1/30/2024



Photo 42 - Open excavation 1/30/2024

Inspection Photos
Pan Am B 4,6,10,12
Spill ID 485939



Photo 43 – Soil stockpile 1/30/2024



Photo 44 - Soil stockpile 1/30/2024