

Final Reclamation Inspection

January 30th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333634

Inspection Document #: 714000369

La Plata County, CO

Township: NWSE 7 34N 7W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Laurance Jones A 1, A 3

Location ID: 333634



Photo 1. View of the disturbance from the entrance facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07854, 09659

Inspection Photos

Location Name: Laurance Jones A 1, A 3

Location ID: 333634



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the eastern and western interim reclamation areas. Weed corrective action observed in previous inspection have been addressed/resolved.

API #: 067-07854, 09659

Inspection Photos

Location Name: Laurance Jones A 1, A 3

Location ID: 333634



Photo 3. View of surface owner trailers, trucks and farm equipment stored within the northern interim reclamation area and unused metal debris stored in the southern portion of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07854, 09659