

# Final Reclamation Inspection

January 30th, 2024

Operator: Simcoe LLC - 10749

Location ID: 334338

Inspection Document #: 714000374

La Plata County, CO

Township: SWSE 9 34N 7W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Knight E2, E3  
Location ID: 334338



**Photo 1.** View of the disturbance from the entrance facing center. Missing sign CA observed in FIR Form #712700647 has been addressed.



Inspection Photos  
Location Name: Knight E2, E3  
Location ID: 334338



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of the western interim reclamation area.

API #: 067-09021, 09654



Inspection Photos  
Location Name: Knight E2, E3  
Location ID: 334338

1/30/24  
+37.201969,-107.609891  
289° W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Musk thistle observed in the northwest interim reclamation area.

API #: 067-09021, 09654



Inspection Photos  
Location Name: Knight E2, E3  
Location ID: 334338



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Unused oil and gas equipment observed on location.

API #: 067-09021, 09654